



PLANTA POTABILIZADORA PASTOR LOZANO

ANÁLISIS FÍSICOQUÍMICOS
AGUA CRUDA RIO BRAVO
ABRIL 2023

RESULTADOS EN MG/LT

FECHA:	3	4	5	6	7	10	11	12	13	14	17	18	19	20	21	24	25	26	27	28	PROMEDIO
TURBIDEZAD N.T.U.	29.3	34.3	31.9	39.3	35.5	20.6	18.9	22.1	23.3	23.2	22.6	19.8	16.3	18.4	18.3	29.6	27.5	25.3	24.6	18.2	25.0
P.H.	7.1	8.1	8.0	7.1	7.9	8.1	7.5	8.1	7.8	7.1	7.1	7.2	7.0	6.9	7.0	7.3	7.2	7.0	7.4	7.2	7.4
ALCALINIDAD TOTAL	116	128	120	132	136	132	120	128	114	130	122	126	120	116	122	130	128	120	124	122	124
DUREZA TOTAL	284	296	280	268	290	290	302	302	304	378	356	360	368	372	380	320	336	358	320	310	323
DUREZA DE CALCIO	136	148	140	130	144	154	176	162	140	156	174	172	178	188	200	160	164	180	164	150	161
DUREZA DE MAGNESIO	148	148	140	138	136	136	126	140	164	222	182	188	190	184	180	160	172	178	156	160	162
CLORUROS	120	110	112	108	123	125	130	142	138	140	133	138	136	130	126	114	122	128	120	126	126
SDT	400	421	396	378	370	531	581	556	580	554	580	596	560	456	465	500	588	586	502	520	505
TEMPERATURA OC	24.7	23.4	24.5	21.1	19.8	21.0	21.2	20.7	21.5	23.2	24.8	23.6	23.2	23.7	23.6	22.0	23.3	24.1	23.6	24.0	22.9

AUTORIZO:

I.Q. TERESITA BERNARDEZ LOPEZ MELGAR
JEFA DEL LABORATORIO

BISLADO GALJERMO NAVAJUANO
COORDINADOR DE CALIDAD DEL AGUA

Rio Panuco S/N, esq. José de Escandón
Col. Longoria
Cd. Reynosa, Tamaulipas, México
www.comapareynosa.gob.mx

