

PLANTA POTABILIZADORA PLANTA PASTOR LOZANO

ANALISIS FISICOQUIMICOS
 AGUA POTABLE
 OCTUBRE 2018

RESULTADOS EN MG/LT																														
FECHA:	1	2	3	4	5	8	9	10	11	12	15	16	17	18	19	22	23	24	25	26	29	30	31	NOM-127/94	PROMEDIO					
TURBIEDAD NTU	5.0	4.0	5.0	5.0	3.3	3.4	4.0	5.0	5.0	4.9	5.0	4.8	5.0	5.0	3.9	5.0	3.8	4.0	4.3	3.5	3.9	5.0	5.0	5.0	5 NTU	4.5				
PH	7.4	7.5	7.2	7.3	7.4	7.3	7.3	7.2	7.1	7.2	7.3	7.1	7.1	7.2	7.4	7.1	7.3	7.2	7.3	7.3	7.3	7.3	7.3	7.2	6.5-8.5	7.3				
ALCALINIDAD TOT	108.0	120.0	114.0	96.0	98.0	98.0	112.0	96.0	102.0	86.0	110.0	102.0	118.0	114.0	120.0	110.0	102.0	100.0	106.0	96.0	118.0	112.0	120.0		106.9					
DUREZA TOTAL	362.0	370.0	356.0	324.0	300.0	262.0	272.0	290.0	262.0	288.0	290.0	300.0	328.0	352.0	362.0	368.0	372.0	354.0	344.0	346.0	361.0	366.0	340.0	500 mg/L	328.2					
CLORUROS	324.0	355.0	317.0	284.0	233.0	245.0	274.0	273.0	227.0	239.0	234.0	236.0	250.0	285.0	287.0	285.0	288.0	290.0	250.0	212.0	270.0	270.0	270.0	250 mg/L	269.5					
CLORO RESIDUAL	1.3	1.0	1.2	1.4	1.0	1.4	1.5	1.0	1.0	1.1	1.0	1.0	1.3	1.0	1.2	0.9	1.5	1.5	1.5	1.5	1.5	1.5	1.5		1.2					
CALCIO	202	198	180	182	170	158	170	180	148	170	146	160	208	204	194	218	234	200	208	210	134	220	210		186.3					
MAGNESIO	160	172	176	142	130	104	102	130	114	98	144	140	120	148	168	150	138	154	136	136	156	146	130		138.9					
SDT	886	1170	1198	900	1017	1005	975	1050	900	978	686	669	725	768	753	802	776	705	666	635	807	682	678	1000 mg/lit	844.8					
TEMPERATURA °C	26.5°C	25.8°C	26.1°C	25.6°C	25.6	27.3	27.4°C	26.9°C	27°C	26.7°C	27.4°C	22°C	20.5°C	20.3°C	19.9°C	21.3°C	18.8°C	19.9°C	20.3°C	20.7°C	24.5°C	23.1°C	23.9°C		26.5					

AUTORIZO:

QIF. MIRIAM CAVAZOS GARCIA
 RESPONSABLE DE LABORATORIO

BIOTOF. EULIERTO NAVA LUJANO
 COORDINADOR DE CALIDAD DEL AGUA

Vo.Bo.



Río Panuco S/N. 889 José de Escandón
 Col. Longoria
 Cd. Reynosa, Tamaulipas, México
 www.comapareynosa.gob.mx