

PLANTA POTABILIZADORA PASTOR LOZANO

ANALISIS FISICOQUIMICOS
AGUA CRUDA
SEPTIEMBRE 2019

RESULTADOS EN MG/LT

FECHA:	2	3	4	5	6	9	10	11	12	13	16	17	18	19	20	23	24	25	26	27	30	NOM- 127/94	PROMEDIO
TURBIEDAD N.T.U.	16.4	14.0	12.4	16.0	16.0	12.9	13.5	12.8	12.3	12.4	12.8	9.7	13.40	12.9	16.0	13.1	14.0	13.1	12.6	12.1	12.6	5 NTU.	13.4
PH	7.9	7.8	7.9	7.8	7.6	7.7	7.9	7.8	7.9	7.7	7.6	7.6	7.6	7.7	7.6	7.9	7.5	7.6	7.7	7.8	7.8	6.5-8.5	7.7
ALCALINIDAD TOTAL	52	50	60	56	54	46	64	64	78	62	98	60	62	86	80	52	62	60	90	84	56		65.5
DUREZA TOTAL	190	252	340	276	250	226	274	256	254	260	296	236	296	324	260	230	180	260	280	298	290	500 MG/L	263.2
CLORUROS	135	175	190	159	197	182	170	165	170	153	171	179	196	210	242	166	155	194	180	172	171	250 MG/L	177.7
DUREZA DE CALCIO	156	150	190	168	168	136	170	150	146	146	172	138	174	302	240	150	196	146	180	190	190		174.2
D. DE MAGNESIO	34	102	150	168	82	90	104	106	120	114	124	98	122	22	20	80	84	114	100	102	100		97.0
SDT	499	510	571	461.5	487.5	778	700.5	684	683	562	560	540	598	642	360	587	722	474	606	594	611	1000 MG/LT	582.4

AUTORIZO:

Q.F.B. MIRIAM CAVAZOS GARCIA
RESPONSABLE DE LABORATORIO

Vo. Bo
BIÓLOGO QUIJERO NAVA LUANO
COORDINADOR DE CALIDAD DEL AGUA



Río Pánuco S/N, esq. José de Escandón
Cd. Longoria
Cd. Reynosa, Tamaulipas, México
www.comapareynosa.gob.mx