


PLANTA POTABILIZADORA PASTOR LOZANO


ANALISIS FISICOQUÍMICOS  
AGUA POTABLE  
NOVIEMBRE 2019

RESULTADOS EN MGLT

FECHA:	1	4	5	6	7	8	11	12	13	14	15	19	20	21	22	25	26	27	28	29	NOM-127/94	PROMEDIO
TURBIEDAD N.T.U.	5.0	5.0	5.0	4.6	4.9	5.0	4.8	5.0	5.0	5.0	4.4	5.0	5.0	3.1	4.8	4.9	5.0	5.0	4.8	5.0	5 NTU.	4.8
P.H.	7.2	7.2	7.2	7.2	7.4	7.3	7.4	7.4	7.5	7.6	7.5	7.5	7.6	7.6	7.6	7.5	7.5	7.6	7.5	7.4	6.5-8.5	7.4
ALCALINIDAD TOTAL	100	120	104	108	110	122	124	118	116	124	126	98	122	114	126	112	160	122	130	142		119.9
DUREZA TOTAL	244	280	332	250	266	228	248	320	344	300	259	390	302	342	24	304	256	280	352	286	500 MG/LT	280.4
CLORUROS	170	165	179	170	168	180	180	186	190	188	190	176	201	179	180	190	202	210	225	215	250 MG/LT	187.2
COLORO RESIDUAL	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.2	1.2	1.2	1.0	1.0	1.3	1.0	1.0	1.0	1.5	1.4	1.0	1.0	0.2-1.5MG/LT	1.26
DUREZA DE CALCIO	166	160	178	154	160	146	164	199	188	175	170	186	194	212	156	142	202	160	158	184		172.7
D. DE MAGNESIO	78	120	154	96	106	82	84	121	156	125	89	204	108	130	84	162	54	120	194	102		118.5
SDT	585	596	757	691	635	638	503	698	723	743	598	500.5	641	621	618	664	690	679	675	608	1000 MG/LT	643.2



Rto Pánuco S/N, esq. José de Escandón  
Col. Longoria  
Cd. Reynosa, Tamaulipas, México  
www.comapareynosa.gob.mx



Vo. B.

BIOLOGO GUILLERMO NAYA LUJANO  
COORDINADOR DE CALIDAD DEL AGUA