



AYUNTAMIENTO
REYNOSA
2018 - 2021

COMADIA

PLANTA POTABILIZADORA PASTOR MONTE

ANÁLISIS FÍSICOQUÍMICOS
AGUA CRUDA
ENERO 2020



Tam
TAMAUlipas

RESULTADOS EN MG/LT

FECHA:	2	3	6	7	8	9	10	13	14	15	16	17	20	21	22	23	24	27	28	29	30	31	NOM-127/94	PROMEDIO
TURBIEDAD N.T.U.	11.3	10.3	10.6	11.1	11.2	11.2	13.1	12.4	12.1	10.7	12.0	12.1	14.7	11.5	13.8	12.9	12.0	12.8	11.5	11.0	13.4	12.8	5 NTU.	12.0
P.H.	7.7	7.7	7.5	7.4	7.6	7.6	7.4	7.6	7.6	7.6	7.7	7.2	7.5	7.5	7.6	7.7	7.4	7.6	7.4	7.5	7.6	7.6	6.5-8.5	7.5
ALCALINIDAD TOTAL	130	126	120	130	136	140	126	136	150	134	146	152	148	144	140	142	146	148	140	158	144	148		140.2
DUREZA TOTAL	328	320	320	420	270	260	280	272	240	296	252	296	302	312	284	310	346	300	280	276	320	326	500 MG/LT	300.5
DUREZA DE CALCIO	234	240	260	226	90	160	168	188	180	212	170	170	180	204	174	194	204	176	202	156	180	200		189.5
D. DE MAGNESIO	94	80	60	194	180	100	112	84	60	84	82	126	122	108	110	116	142	124	78	120	140	126		111.0
CLORUROS	200	204	198	210	214	198	210	206	193	202	200	205	208	205	202	209	206	210	209	205	165	170	250 MG/LT	201.3
SDT	653	663	689	672	647	600	569	677.5	783.5	689.5	700	707	707	716	565	582	575	549	841	670	652	603	1000 MG/LT	659.6

AUTORIZÓ:

QFB. MIRIAM CAVAZOS GARCIA
RESPONSABLE DE LABORATORIO

Vo.Bo.
BIOLOGO GUILLERMO NAVA LUJANO
COORDINADOR DE CALIDAD DEL AGUA