



AYUNTAMIENTO
REYNOSA
2018 - 2021



PLANTA POTABILIZADORA PASTOR LOZANO

ANALISIS FISICOQUÍMICOS AGUA POTABLE MARZO 2020

RESULTADOS EN MG/LT

FECHA:	2	3	4	5	6	9	10	11	12	13	17	18	19	20	23	24	25	26	27	30	31	NOM-127/94	PROMEDIO
TURBIEDAD N.T.U.	4.5	3.0	4.1	2.2	4.4	3.1	5.0	5.0	5.0	3.4	5.0	5.0	5.0	2.8	5.0	5.0	4.7	5.0	2.8	2.5	5.0	5 NTU	4.2
P.H.	7.2	7.1	7.1	7.0	7.0	7.5	7.0	7.2	7.1	7.1	7.2	7.1	7.1	7.5	7.2	7.1	7.2	7.2	7.5	7.0	6.8	6,5-8,5	7.2
ALCALINIDAD TOTAL	122	114	108	108	114	108	110	108	106	110	116	120	110	114	116	114	108	124	108	100	100		111.3
DUREZA TOTAL	340	342	318	342	314	348	350	308	320	302	332	326	324	326	334	308	342	326	330	306	350	500 MG/LT	328.0
DUREZA DE CALCIO	180	206	200	210	220	264	250	212	210	194	222	190	202	188	202	190	214	184	182	186	198		205.0
D. DE MAGNESIO	160	136	118	132	94	84	100	96	110	108	110	136	122	138	132	118	128	142	148	120	152		123.0
CLORUROS	210	185	199	188	189	140	204	189	200	187	181	191	208	188	193	184	188	200	199	197	250	250 MG/LT	193.8
CLORO RESIDUAL	1.5	1.5	1.5	1.5	1.5	1.5	1.5	1.4	1.3	1.5	1.5	1.5	1.5	1.5	0.9	1.5	1.5	1.5	1.5	1.5	1.5		1.5
SDT	604	597.5	520.5	514	584.5	537	515	567	561.5	565	644	523	516	518	769	756	657	562	585	589	638	1000 MG/LT	586.7

AUTORIZÓ:

QFB. MIRIAM CAVAZOS GARCIA
RESPONSABLE DE LABORATORIO



Vo.Bo.
BIÓLOGO GUILLERMO NAVA LUJANO COORDINADOR
DE CALIDAD DEL AGUA



Río Pánuco S/N, esq. José de Escandón
Col. Longoria
Cd. Reynosa, Tamaulipas, México
www.comapareynosa.gob.mx