



AYUNTAMIENTO
REYNOSA
2018 - 2021



PLANTA POTABILIZADORA PASTOR LOZANO

ANÁLISIS FÍSICOQUÍMICOS AGUA CRUDA CANAL RODHE JUNIO 2021

RESULTADOS EN MG/LT

FECHA:	1	2	3	4	7	8	9	10	11	14	15	16	17	18	21	22	23	24	25	28	29	30	PROMEDIO
TURBIEDAD N.T.U.	16.2	25.4	23.0	19.3	16.4	16.2	16.8	19.3	22.0	21.0	22.4	23.2	25.3	20.4	21.3	19.5	18.8	17.0	22.2	25.1	20.0	18.5	20.4
P.H.	7.3	7.5	7.6	7.4	7.5	7.7	7.4	7.5	7.4	7.5	7.4	7.2	7.3	7.4	7.5	7.6	7.6	7.4	7.4	7.5	7.4	7.3	7.4
ALCALINIDAD TOTAL	112	106	104	124	126	122	128	130	128	129	126	121	116	110	104	94	128	120	126	116	110	112	118
DUREZA TOTAL	376	354	318	332	358	368	360	354	342	340	338	332	336	340	346	340	360	344	334	342	340	330	345
DUREZA DE CALCIO	240	220	196	218	220	222	210	206	202	198	200	197	158	204	208	184	190	168	170	174	178	170	197
D. DE MAGNESIO	136	134	122	114	138	146	150	148	140	142	138	135	178	136	138	156	170	176	164	168	162	160	148
CLORUROS	205	200	172	182	192	190	189	195	190	210	206	200	198	194	200	193	197	196	195	190	184	176	193
SDT	625	562	582	542	573	580	585	590	600	836	833	826	839	800	635	799	923	594	580	572	570	600	666
TEMPERATURA °C	27.9	26.2	26.7	25.6	28.0	28.4	28.9	29.2	28.9	30.2	30.4	30.6	28.2	28.9	29.5	29.9	28.9	29.0	29.4	29.6	28.3	26.7	29

AUTORIZÓ:

I.Q. BERENICE LOPEZ MELGAR
RESPONSABLE DE LABORATORIO

Vo.Bo.

BIOLOGO GUILLERMO NAVA LUJANO
COORDINADOR DE CALIDAD DEL AGUA

Río Pánuco S/N, esq. José de Escandón
Col. Longoria
Cd. Reynosa, Tamaulipas, México
www.comapareynosa.gob.mx